

Work Order ID 70634

Page 1

Friday, June 10, 2011 2:28:47 PM

Item ID: D412-702-311

Accept



Setup Start



Revision ID:

Stop



Item Name: Harness Assembly

Start Date: 6/10/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 6/22/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

6/10/10

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

DSI 9511

A

100

0.00



Small Fab

Memo

0.00

Small Fab

Assemble as per dwg ICA D412-702 p.49

110

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

Quality Control

120

0.00



Packaging

Memo

0.00

Packaging

Identify with P/N & CHG# and pack for shipping as per PPP D412-702-311

CHG001

Location: 267

PPP Rev: _____

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 70634

Friday, June 10, 2011 2:28:47 PM



Page 2

Item ID: D412-702-311

Accept



Setup Start



Revision ID:

Stop



Item Name: Harness Assembly

Start Date: 6/10/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 6/22/2011 Req'd Qty: 1.00



Customer:

Reference:

Run Start



Approvals:

Process Plan: _____

Date: _____

Tooling: _____

Date: _____

Stop



QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

11/6/14

MF
11-06-15

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Friday, June 10, 2011 2:28:54 PM

Page 1

Work Order ID: 70634

Parent Item: D412-702-311

Parent Item Name: Harness Assembly



Start Date: 6/10/2011

Required Date: 6/22/2011

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:A new issue DD 10.04.30 verified:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3570-1 Bracket		Manufactured	No			100	Each	13.0000	1	1			
				<u>Location</u>			<u>Loc Qty</u>	<u>Loc Code</u>					
				GA			13						
					55311		13						
D4088-043 Shoulder Harness		Manufactured	No			100	Each	13.0000	1	1			
				<u>Location</u>			<u>Loc Qty</u>	<u>Loc Code</u>					
				ST267			10						
					69597		10						
				ST272A			3						
					68874		3						
MS24694-S50 Screw		Purchased	No			100	Each	101.0000	4	4			
				<u>Location</u>			<u>Loc Qty</u>	<u>Loc Code</u>					
				ST289			50						
					117739		50						
				ST298			51						
					116900		51						
AN960JD10L Washer	NAS1149D0332J	Purchased	No			100	Each	0.0000	4	4			
				<u>Location</u>			<u>Loc Qty</u>	<u>Loc Code</u>					

4D M117291 (40)

EP 11/06/13

EP 11/06/13

4 1

EP 11/06/13

4
EP 11/06/13

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Friday, June 10, 2011 2:28:55 PM

Page 2

Work Order ID: 70634



Parent Item: D412-702-311



Parent Item Name: Harness Assembly

Start Date: 6/10/2011

Required Date: 6/22/2011

Start Qty: 1.00

Required Qty: 1.00

MS21042L3

Purchased

No

100

Each

2,307.000

4



Nut



EP 11/06/13

Location

Loc Qty

Loc Code

ST300

2307

108701

12

116391

9

116549

586

117441

800

117601

400

117885

500

4

Friday, June 10, 2011 2:28:55 PM

Shop Packet Print

Page 2


W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



**DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND
D412-702-101B/-103B/-105B/-107B/-109B/-115B/-117B OR -301/-303/-305/-
307/-309/-315/-317 HARNESS ASSEMBLIES**



SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 70639
11-06-10

DETAIL 'L' D412-702-111A/-111B/-113A/-113B OR -311/-313/-321/-323 HARNESS ASSEMBLIES

• COPYRIGHT © 2004 BY DART AEROSPACE LTD. •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR
COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

25-00-00

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries